

Technical Bulletin

GX/HX BLOWER SHIPPING BRACKET

Date: April 23, 2010


Tech Bulletin #: TB10.002

Enertech Manufacturing has added a blower shipping bracket on the opposite side of the blower motor that needs to be removed before start up. *This only applies to Compass and Revolution vertical units.*

The attachment shows the location of the shipping bracket.

THIS BRACKET MUST BE REMOVED.

Remove the two (2) screws shown and then slide the shipping bracket off the motor shaft before unit start up. Dispose of the bracket and the screws.



REMOVAL OF SHIPPING BRACKET