



2506 South Elm Street  
Greenville, IL 62246  
www.enertechgeo.com  
(888)-436-3783

## Technical Bulletin

Contactors

June 21, 2012  
TB12.006

This is to serve as a notice of quality issue with contactors used in product manufactured by Enertech Global. The contactors have failed in a similar manner as shown below. The arm that secures the floating contacts has physically broke, causing the part to fail. The amount of unit run times has varied with each report.

Enertech has changed the supplier of the contactor after investigation of the failure. Product manufactured after June 2012 (serial number M1206xxxx) will have a contactor from the new supplier. The new contactor retains the part number 11430001001.

Please follow the normal warranty procedure for failures.

