



2506 South Elm Street  
Greenville, IL 62246  
www.enertechgeo.com  
(888)-436-3783

## Technical Bulletin

Soft Start Kit Wire Harness

October 4, 2012

TB12.009

This is to serve as a notice that the wire harness in the soft start kit may be wired incorrectly. Soft start kits with part numbers AKSSSC, AKSSLC should be checked to verify the 4 pin connector is wired properly.

The 4 pin connector should be wired where the red wire is in position number 1, the green wire in position 2, the yellow wire in position 3, and the black wire in position 4 as shown in the figure below. The position numbers are molded into the plastic housing. The wire harness will mate in the control box and the colors should correspond.

If you find a miswired kit, please contact Enertech Global for a replacement harness.

