



2506 South Elm Street
Greenville, IL 62246
www.enertechgeo.com
(888)-436-3783

Technical Bulletin

Blower Motor on Hydronic Air Handler

October 22, 2012
TB 12.010

This is to serve notice for the ECM blower motors used in the hydronic air handler (MPH Series) not performing at the intended motor speeds.

Any unit with a serial number before R061512XXXX will not produce the correct airflow if the W2 terminal or the EM terminal are energized. The motor program will reduce the airflow output and possibly activate the high temperature limit in the electric heater kit, if a heater kit is present.

If you have a unit that is in the suspect range, and are experiencing airflow issues, please contact Technical Support for assistance at 618-664-5860.